INSTALLATION INSTRUCTIONS

IMPORTANT SAFEGUARDS

Read & Follow All Safety Instructions

When using electrical equipment, basic safety precautions should always be followed including:

- 1. Disconnect power before performing work on electrical equipment (using the light switch to turn off the power is not sufficient to prevent electrical shock)
- 2. Do not use outdoors
- 3. Do not mount near gas or electric heaters
- 4. Do not install in unstable, loose or breakable surfaces and do not let objects impact or exert force on the surface of the fixture
- 5. Use caution when servicing batteries (Battery acid can cause burns to skin and eyes; if acid is spilled on skin or eyes, flush with water and contact a physician immediately)
- 6. Equipment should be mounted in locations and at heights where it will not be subjected to tampering by unauthorized personnel
- 7. The use of accessory equipment not recommended by Beghelli Inc may cause an unsafe condition and will void the unit's warranty
- 8. Do not use this equipment for the other than its intended purpose
- 9. Installation and servicing of this equipment should be performed by a qualified electrician familiar with the product and the hazards involved
- 10. Allow battery to charge for 24 hours before first use
- 11. To prevent wiring damage or abrasion, do not expose wiring to edges of sheet metal or other sharp objects

WARNING

- 1. Verify correct supply voltage by comparing it with the luminaire label information
- 2. All wiring connections should be capped with UL approved wire connectors
- 3. Use minimun 90° C Supply Wires


- 1. Avoid direct eye exposure to the light source while it is on
- 2. Beware small parts and packing material may be hazardous to children
- 3. Risk of burn; Disconnect power and allow fixture to cool before handing fixture

SAVE THESE INSTRUCTIONS


SURFACE MOUNT (STANDARD)

Surface Mount Clip Attach surface mount clips to mounting surface 1. (ceiling or wall) Surface Mount Clip Flange Snap fixture onto mounting clips 2 Make electrical connections (see wiring diagram 3. Flange Housing on pg 4) Mounting Bracket BS101 LED 4FT BS100 LED 4FT & 2FT

AIRCRAFT CABLE (AC)



- 1. Attach the cable glider to the surface mount clip using provided locknut as shown
- Snap the assembly onto the mounting bracket on the housing (BS100 or BS101)
- 3. Thread the aircraft cable through the cable glider as shown
- 4. Push top sleeve of cable glider to release lock and adjust level
- 5. Make electrical connections as shown on pg 4 (see canopy & wiring diagrams)







CHAIN HANG (2CH48)




- 1. Insert the hook clip through the loop of the chain
- 2. Attach the hook clip onto the holes on the top of the mounting bracket on the housing as shown
- 3. Make electrical connections (see wiring diagram on pg 4)



IP66 JUNCTION MOUNT (JM)



- 1. Attach the mounting clips to the ceiling as shown
- 2. Wire connections to the J-box
- 3. Snap the fixture onto the mounting clips on the wall/ceiling
- 4. Make electrical connections (see wiring diagram on pg 4)



MAGNET MOUNT (MM)



- 1. Snap the magnet assembly onto the fixture
- 2. Mount the fixture to the metal surface of the main structure
- 3. Attach the eyelet of the safety cable to the main structure of the building with provided screw & locknut
- 4. Make electrical connections (see wiring diagram on pg 4)


NOTE:

Magnetic mounts must be installed to steel beam measuring minimum 3/16" (4.7mm) thick






PIVOT MOUNT (PM)




SINGLE PENDANT KIT (1PKxWBS02, 1PKxWBS04, 1PKxWBS14, 1SPKxWBS02, 1SPKxWBS04, 1SPKxWBS14*)







IP66 QUICK MOUNT BRACKET (QMBWBS04)




- 1. Attach the quick mounting bracket assembly to the J-box & ceiling as shown
- 2. Make electrical connections in the J-box (see wiring diagram below)
- 3. Snap the fixture onto the quick mount bracket assembly



TRUNNION MOUNT KIT (TM22BS04, TM22BS02, TM22BS14)




CANOPIES



NOTE: Twist the canopy for the tab to engage with slotted hole on canopy

WIRING DIAGRAM



0-10V dimming wires must be run from a different conduit out of the J-box